

## ADVISORY

DATE: February 20, 2018

### PRODUCTS AFFECTED: Car-O-Liner Scissors Lift

PART NUMBER(s): Mark 6

## WARNING

There is a possibility of a weld failure at the bottom of the outer scissors arm. The weld failure could be caused by a severe overload, uneven loading, lack of maintenance or an imperfect weld. A weld failure in this area can result in a collapse of the lift under load, resulting in property damage and/or personal injury.

### ACTIONS:

1. Inspect these welds in accordance with the “**Mark 6 Weld Check Instructions**” link below. Do not use a Lift that fails to comply with these requirements until it is replaced or repaired.
2. Perform an inspection, lubrication and routine maintenance in accordance with the “**Mark 6 Inspection and Service Plan**” link

Select the following Links:

[Mark 6 Weld Check Instructions >](#)

[Mark 6 Inspection and Service Plan >](#)



## QUESTIONS:

If you have questions on this advisory or need assistance contact: [inspection@car-o-liner.se](mailto:inspection@car-o-liner.se)