

PRODUCT SAFETY

Snap-on Incorporated

RECALL

February 27, 2012

PRODUCTS AFFECTED: Blue-Point Battery Maintainer

PART NUMBER(s): **EEBM100**




HAZARD:

The safety defect involves a potential short circuit between the vehicle battery and the maintainer when charging the battery. The heat generated by the short circuit could cause the plastic and/or output cables to melt, increasing the risk of fire.

ACTIONS:

- 1) You should immediately discontinue using the Blue-Point Battery Maintainer, model EEBM100, and return it to Clore Automotive.
- 2) Call Clore Automotive customer service at 800-328-2921 or go to www.cloreinfo.com/return and complete form to request a prepaid UPS mailing label to return the product.
- 3) To confirm that your maintainer is one of these models, look for the model number on the product located on the back of the unit.



- 4) Upon receipt of the return of your Blue-Point battery maintainer, **Clore Automotive will ship to you free of charge, a new Snap-on model EEBM500**. It has 4 amps with added features and can be reviewed at www.snapon.com.

QUESTIONS:

If you have questions on this advisory or need assistance contact: Clore Automotive at **1-800-328-2921**.